



Photographic Documentation
ERRS USS Lead Zone 2
Exhibit A
Property ID: 2547
Property Address: Kennedy Gardens



Area: 1
Species:
 Ailanthus

Condition:
 Good

Request:
 Removal & Replace w/like
 and kind (Smaller Tree).

**All volunteer trees and
 all shrubbery to be
 removed.**



**Replacement Locations
 to be determined.**



EPA Approval: _____ East Chicago Approval: _____ ER Approval: _____





Photographic Documentation
ERRS USS Lead Zone 2
Exhibit A
Property ID: 2547
Property Address: Kennedy Gardens

<p>Area: 2 & 3 Species: Siberian Elm</p> <p>Condition: Fair</p> <p>Request: Removal & Replace w/like and kind (Smaller Trees).</p> <p>All volunteer trees and all shrubbery to be removed.</p> <p>Replacement Locations to be determined.</p>	
<p>Area: 4 Species: Mulberry</p> <p>Condition: Good</p> <p>Request: Removal & Replace w/like and kind (Smaller Tree).</p> <p>All volunteer trees and all shrubbery to be removed.</p> <p>Replacement Locations to be determined.</p>	

EPA Approval: _____ East Chicago Approval: _____ ER Approval: _____





Photographic Documentation
ERRS USS Lead Zone 2
Exhibit A
Property ID: 2547
Property Address: Kennedy Gardens

<p>Area: 5</p> <p>Species: Cluster-Siberian Elm, Mulberry, Ailanthus</p> <p>Condition: Good</p> <p>Request: Removal & Replace w/like and kind (Smaller Trees).</p> <p>All volunteer trees and all shrubbery to be removed.</p> <p>Replacement Locations to be determined.</p>	
<p>Area: 6</p> <p>Species: Mulberry</p> <p>Condition: Good</p> <p>Request: Removal & Replace w/like and kind (Smaller Tree).</p> <p>All volunteer trees and all shrubbery to be removed.</p> <p>Replacement Locations to be determined.</p>	

EPA Approval: _____ East Chicago Approval: _____ ER Approval: _____





Photographic Documentation
ERRS USS Lead Zone 2
Exhibit A
Property ID: 2547
Property Address: Kennedy Gardens

<p>Area: 7 Species: Cluster-Crabapple, Mulberry</p> <p>Condition: Good</p> <p>Request: Removal & Replace w/like and kind (Smaller Trees).</p> <p>All volunteer trees and all shrubbery to be removed.</p> <p>Replacement Locations to be determined.</p>	
<p>Area: 8 Species: Siberian Elm</p> <p>Condition: Fair</p> <p>Request: Removal & Replace w/like and kind (Smaller Tree).</p> <p>All volunteer trees and all shrubbery to be removed.</p> <p>Replacement Locations to be determined.</p>	

EPA Approval: _____ East Chicago Approval: _____ ER Approval: _____





Photographic Documentation
ERRS USS Lead Zone 2
Exhibit A
Property ID: 2547
Property Address: Kennedy Gardens

<p>Area: 9 Species: Walnut</p> <p>Condition: Good</p> <p>Request: Removal & Replace w/like and kind (Smaller Tree).</p> <p>All volunteer trees and all shrubbery to be removed.</p> <p>Replacement Locations to be determined.</p>	
<p>Area: 10 Species: Flagpole Cluster-Siberian Elm, Hawthorn</p> <p>Condition: Good</p> <p>Request: Removal & Replace w/like and kind (Smaller Trees).</p> <p>All volunteer trees and all shrubbery to be removed.</p> <p>Replacement Locations to be determined.</p>	

EPA Approval: _____ East Chicago Approval: _____ ER Approval: _____





Photographic Documentation
ERRS USS Lead Zone 2
Exhibit A
Property ID: 2547
Property Address: Kennedy Gardens

<p>Area: 11</p> <p>Species: Crabapple</p> <p>Condition: Fair</p> <p>Request: Removal & Replace w/like and kind (Smaller Tree).</p> <p>All volunteer trees and all shrubbery to be removed.</p> <p>Replacement Locations to be determined.</p>	
<p>Area: 12</p> <p>Species: Catalpa</p> <p>Condition: Good</p> <p>Request: Save</p> <p>All volunteer trees and all shrubbery to be removed.</p> <p>Replacement Locations to be determined.</p>	

EPA Approval: _____ East Chicago Approval: _____ ER Approval: _____




Photographic Documentation
ERRS USS Lead Zone 2
Exhibit A
Property ID: 2547
Property Address: Kennedy Gardens


<p>Area: 13 Species: Siberian Elm</p> <p>Condition: Poor</p> <p>Request: Removal & Replace w/like and kind (Smaller Trees).</p> <p>All volunteer trees and all shrubbery to be removed.</p> <p>Replacement Locations to be determined.</p>	 A black and white photograph of a large, mature tree with a thick trunk and a wide, spreading canopy. The tree is situated in a grassy field. In the background, there are other trees and a body of water under a cloudy sky.
<p>Area: 14 Species: Siberian Elm</p> <p>Condition: Poor</p> <p>Request: Removal & Replace w/like and kind (Smaller Trees).</p> <p>All volunteer trees and all shrubbery to be removed.</p> <p>Replacement Locations to be determined.</p>	 A black and white photograph showing several trees of varying heights in a grassy field. The trees have thin trunks and dense foliage. In the background, there are more trees and a body of water under a cloudy sky.

EPA Approval: _____ East Chicago Approval: _____ ER Approval: _____



Photographic Documentation
ERRS USS Lead Zone 2
Exhibit A
Property ID: 2547
Property Address: Kennedy Gardens



<p>Area: 15</p> <p>Species: Norway Spruce</p> <p>Condition: Fair</p> <p>Request: Removal & Replace w/like and kind (Smaller Trees).</p> <p>All volunteer trees and all shrubbery to be removed.</p> <p>Replacement Locations to be determined.</p>	
--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------

<p>Area: 16</p> <p>Species: Siberian Elm</p> <p>Condition: Fair</p> <p>Request: Removal & Replace w/like and kind (Smaller Trees).</p> <p>All volunteer trees and all shrubbery to be removed.</p> <p>Replacement Locations to be determined.</p>	
-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	--------------------------------------------------------------------------------------

EPA Approval: _____ East Chicago Approval: _____ ER Approval: _____



Photographic Documentation
ERRS USS Lead Zone 2
Exhibit A
Property ID: 2547
Property Address: Kennedy Gardens

<p>Area: 17 Species: Siberian Elm</p> <p>Condition: Poor</p> <p>Request: Removal & Replace w/like and kind (Smaller Trees).</p> <p>All volunteer trees and all shrubbery to be removed.</p> <p>Replacement Locations to be determined.</p>	
<p>Area: 18 Species: Cluster-Basswood, Ailanthus</p> <p>Condition: Good</p> <p>Request: Removal & Replace w/like and kind (Smaller Trees).</p> <p>All volunteer trees and all shrubbery to be removed.</p> <p>Replacement Locations to be determined.</p>	

EPA Approval: _____ East Chicago Approval: _____ ER Approval: _____



Photographic Documentation
ERRS USS Lead Zone 2
Exhibit A
Property ID: 2547
Property Address: Kennedy Gardens

<p>Area: 19 Species: Cluster-Ailanthus, Siberian Elm</p> <p>Condition: Good</p> <p>Request: Removal & Replace w/like and kind (Smaller Trees).</p> <p>All volunteer trees and all shrubbery to be removed.</p> <p>Replacement Locations to be determined.</p>	A black and white photograph showing a large, mature tree with a thick trunk and a dense, rounded canopy of leaves. The tree is situated in a grassy area with a sidewalk visible in the foreground.
---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

<p>Area: 20 Species: Cluster-Ailanthus, Siberian Elm</p> <p>Condition: Good</p> <p>Request: Removal & Replace w/like and kind (Smaller Trees).</p> <p>All volunteer trees and all shrubbery to be removed.</p> <p>Replacement Locations to be determined.</p>	A black and white photograph showing a large, mature tree with a thick trunk and a dense canopy. The tree is in a grassy area with a sidewalk and some utility poles visible in the background.
---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

EPA Approval: _____ East Chicago Approval: _____ ER Approval: _____



Photographic Documentation
ERRS USS Lead Zone 2
Exhibit A
Property ID: 2547
Property Address: Kennedy Gardens

Area: 21
Species:
 Cluster-Hackberry, Wild
 Grape vines

Condition:
 Poor

Request:
 Removal & Replace w/like
 and kind (Smaller Trees).

**All volunteer trees and
 all shrubbery to be
 removed.**

**Replacement Locations
 to be determined.**



Area: 22
Species:
 Siberian Elm

Condition:
 Good

Request:
 Removal & Replace w/like
 and kind (Smaller Trees).

**All volunteer trees and
 all shrubbery to be
 removed.**

**Replacement Locations
 to be determined.**



EPA Approval: _____ East Chicago Approval: _____ ER Approval: _____



Photographic Documentation
ERRS USS Lead Zone 2
Exhibit A
Property ID: 2547
Property Address: Kennedy Gardens

Plant Replacement Inventory:

30- Various Hostas
20- Iris Plants
4- Black Eyed Susan
2- Rose of Sharon

Shrub Replacement Inventory:

1- Burning Bush
3- Juniper Bushes

Replacement Locations to be determined.

EPA Approval: _____ East Chicago Approval: _____ ER Approval: _____